





NOTES:

- 2019 AERIAL IMAGE (PROVIDED BY DRUMHELLER RESILIENCY AND FLOOD MITIGATION OFFICE). RIVER € PER NHC (APRIL 2020). PROJECT COORDINATE SYSTEM CANA83-3TM114. TREE LOCATIONS BY RANGELAND (SEPT. 23 2021). SCALE NOTATIONS INDICATED ARE BASED ON AN ANSI B DRAWING FORMAT.
- 2.
- 3.
- 4 5.

		- uller Mr
EXTERNAL TREE H	<u>HEALTH</u>	
VERY GOOD	•	GOOD
FAIR	•	POOR
VERY POOR	•	STUM

OVER HEAD POWER LINE (OPL)

AFFECTED PROPERTY LIMITS

DIKE FOOTPRINT





1:1 250



MIDLAND TREE CLEARING PLAN 3/3